

# )) DR3000 USER GUIDE

## DR3000 features

Auto draft compatible.

Set the large draft/sort indicator to suit your drafting/sorting requirements. Obtain draft/sort statistics for 2, 3 or 4 weight ranges. Use automatic weight recording for hands-free weighing and recording. View past weighing session results with the 100 self-dating files. View all available statistics for a weighing session. Access the built-in manual where and when you need it. Set up the weighing screen display to suit your own weighing requirements. Rearrange draft or recalculate statistic for a weighing session. Print weighing session reports to a computer or serial printer. Use with all Tru-Test load bars and load cells. The back-lit display with light sensor allows the indicator to be used in low light conditions. See how much weighing time is left when running on the internal battery.

1 Mount the indicator bracket on a flat surface, such as a timber rail or concrete structure, using screws or nails. Alternatively, mount the bracket onto horizontal pipework with the U-bolts supplied.

- 2 Connect the load sensor cables to the indicator. Connect the dust caps together to keep out dirt and moisture.
- 3 Connect the power cable (if using an external 12 V supply).

Ensure dust caps are screwed together to keep out dirt and moisture when cables are connected to the indicator. Screw caps back onto the indicator when cables are removed.

Load cell connectors


Communications connector for connecting to computer, printer, auto drafter etc.

Power connector for connecting 12 V vehicle battery (red clip to positive terminal) or Tru-Test power adaptor. To connect power adaptor, pull battery clips off indicator lead and plug lead into power adaptor lead (red to red).

## Installation tips

- 1 Mount the indicator in a convenient place where animals cannot knock the indicator or chew the cables.
- 2 Mount the bracket firmly to prevent possible operator errors or fatigue.
- 3 Position the indicator so that the screen is out of the sun as much as possible.
- 4 When installing load sensors, refer to the documentation supplied with the load sensors.

# INSTALLING THE INDICATOR



# PARTS OF THE INDICATOR

## To turn on the indicator

Press (1) to turn on the indicator. The Startup screen may appear depending on the setup of the indicator.

From the Startup screen, press so to start weighing or press () to access the on-screen tutorial.

Tip: For information on item of interest, move the cursor then press 👔 .

## Weighing screen soft keys

STATS
 Displays average, total, minimum and maximum weights etc.
 FILES
 Displays a list of files. Each file typically represents one weighing session.
 UND
 Clears the last recorded weight.
 ZERO
 Zeroes the scale after build up of dirt on the platform. Normally automatic.

#### **Recording weights**

- Press to turn on the indicator. The Startup screen may appear, depending on the setup of the indicator.
- 2 From the Startup screen, press so to start weighing.
- <sup>3</sup> Press **FILES** to go to the List of Files screen.
- 4 Select an empty file and press (
- 5 Move the animal onto the platform.
- 6 Wait for stable light ) and press .

You have recorded the weight. Repeat steps 5 and 6 for each animal.

# GETTING STARTED

# INDICATOR SETUPS

## Changing options and settings

- 1 Press v to access setup items.
- 2 To change an option or value, highlight the item to be changed and press
- 3 Use the arrow keys to change the option or value and press c to confirm.

## Weighing screen setup

Changing statistics displayed

- 1 Highlight statistics column heading and press
- 2 Use arrows to select statistic.
- 3 Press to confirm.

#### Adding items to weighing screen

- 1 Press x to access setup items.
- 2 Highlight the item to add to weighing screen and press ?
- <sup>3</sup> Press  $\leftarrow$  to highlight  $\ddagger$   $\square$ .
- 4 Press
- 5 Press again to confirm .

## Selecting a file

- 1 Press FILES
- 2 Use the arrow keys to select file number.
- 3 Press to confirm.


The file will be automatically stamped with the current date.

#### Statistics screen

Press **STATS** to view all statistics for the current file.

#### **Drafting Setup screen**

Press X then **DRHFT** to access Drafting Setup .



System Setup		
DAMP SYSTEM : SUPERd	amp III (Cattle)	
WEIGHT RECORDING : Manual	DATE : 02/02/2005	
RESOLUTION: 0.5	TIME : 21#27	
HELD WEIGHT : $\times$	FONT : Original	
AUTO ZERO TRACK : On Net	BACKLIGHT: Off	
POWER UP ZERO : 🗸	CONTRAST : 5	
AUTO POWER OFF : 🗸	STARTUP SCREEN : 🗸	
PROMPT MESSAGE : 🖌		
DRAFT : 🖌	DISABLE POPUPS : X	
DRAFT STATS : 🖌	SOUND : Standard	
DROFT SEPTOL ROTTERY COROLLE CELL COLLEGE		

<ul> <li>During weighing, make sure :</li> <li>The animal has four hooves on the platform.</li> </ul>		WEIGHING TIPS		
	e into contact with the animal, or with part of the enclosure.			
	not touching part of the enclosure. touching an unweighed part of the enclosure.			
• The internal batternal b	ery charger operates from the recommended Tru-Test power adaptor pattery.	BATTERY INFORMATION		
	iches off automatically after 15 minutes of inactivity. Disable this of work of the select X, and select X, to confirm.			
• The indicator show after a period of s	uld be charged for 12 hours before it is used for the first time and storage.			
	formation including Charge (%) and Time to Run (hours ss 🕵 then ERITERY .			
For temperatures	es 8 hours to charge at temperatures of 10 to 35 °C (50 to 95 °F). outside this range, charging time may be increased to 12 hours.			
•	emperatures, the indicator may not change. be left on charge at all times and the scale can be used while charging.			
	derside of the crate or platform is free from dung, dirt and stones.	MAINTENANCE AND STORAGE		
• Store the load bal when not in use.	rs and the indicator in a clean, dry place, out of direct sunlight	TIPS		
Charge the indica	tor before long-term storage, and every six months during storage.	IIFS		
Latest Information For up to date informa for your indicator, visit Service Information For repair or service inf				
Feedback : Tru-Test welcome feedback from customers. You can send any feedback about this product via				
the Feedback link from				
Size	270 x 190 x 71 mm.	SPECIFICATIONS		
Weight	Battery option is 1.6 kg (3½ lb), non battery is 1.4 kg (3 lb).			
Accuracy	1% or 2 resolutions (whichever is greater) when used with Tru-Test load sensors, minimum base resolution 0.5 kg (1 lb) normal, 0.1 kg (0.2 lb) fine.			
Battery	Charging time is 8 hours in normal conditions; Run time is 15 hours continuous use minimum with two load cells (8 hours with back light on). Auto turn off is 15 minutes.			
Power requirements	AC adaptor (regulated) or battery, using crocodile clip 11 to 16 V d.c., 400 mA.			
Display	High contrast, wide temperature LCD module, 240 x 128 dots.			
IP67 rating	The indicator is 100% water and dust proof. Rated for immersion in water to a depth of 1 m for 30 minutes.			
Environmental	Operating temperature: -10 to +40 °C (+15 to +105 °F).			
	Storage temperature: -20 to +35 °C (-5 to +95 °F).			
Load bar capacity Communication	Power for up to 8 (350 $\Omega$ ) load bars or load cells. Enables weighing of large load.			
communication	2 x D9, one interface RS485 or RS232, the other RS232 only. Allows for connection to a printer and/or computer.			
FCC Notice				
This Tru-Test model indicator has been tested and found to comply with the limits for a Class A digital device, pursuant to Part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is used in a commercial environment. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference at their own expense.				

Tru-Test Limited, New Zealand **www.tru-test.com** An ISO 9001 Quality Registered Company